

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




Fig. 1 is a schematic diagram of a mechanical assembly in a perspective view. The assembly includes a base plate 63 with a central pivot 62. A lever 60 is pivoted at 60p on the base. A spring 64 connects the lever to a component 53. A series of gears or pulleys 54, 55, and 56 are connected by a belt 57. A component 51 is connected to the belt system. A handle 61 is attached to the lever. Various other parts are labeled with numbers 50, 52, 53, 58, 59, 59a, 60a, 60p, and 63.

FIG.8




FIG.9A




FIG.9B




FIG.9C




FIG.9D




FIG.10A




FIG.10B




FIG.10C




FIG.10D




FIG.11




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17




FIG.18




FIG.19




FIG.20




FIG.21




FIG.22




FIG.23




FIG.24




FIG.25




FIG.26




FIG.27




FIG.28




FIG.29




FIG.30




FIG. 31




FIG.32




FIG.33




FIG.34




FIG.35




FIG.36




FIG.37

